FIG. 1 PRIOR ART




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16





FIG. 17



MASK-FRAME ASSEMBLY HAVING COMPENSATING UNIT AT INER SIDE OF RESILIENT SUPPORT MEMBERS

FIG. 18





FIG. 18



AT RESPECTIVE FLANGES OF SUPPORT MEMBERS